

TESTING LEAD IN DRINKING WATER SAMPLE CHART

School name: St. John Regional School, Concord

St. John Regional School Concord

SAMPLE ID	DESCRIPTION OF SAMPLE LOCATION	SAMPLE DATE	STAGNANT LEAD, ppb	FOLLOW UP ACTIONS	COMPLETION DATE
192334.01	Main Bldg. Kitchen south faucet	2/22/19	0.0096	none	
192334.02	Main Bldg fountain top floor near grade 5	2/22/19	<0.001	none	
192334.03	Barry Hall fountain on second floor	2/22/19	<0.001	none	
161941.02	Main Bldg. Kitchen north faucet	10/22/16	0.006	none	
161941.03	Main Bldg. cafeteria fountain	10/22/16	0.001	none	
161941.04	Main Bldg. boys room sink ground floor	10/22/16	<0.001	none	
161941.05	Main Bldg. girls room sink ground floor	10/22/16	<0.001	none	
161941.06	Main Bldg. Kindergarten sink	10/22/16	<0.001	none	
161941.07	Main Bldg. Pre-Kindergarten sink	10/22/16	0.002	none	
169141.08	Main Bldg. fountain outside of grade 2 on main floor	10/22/16	<0.001	none	
161941.09	Main Bldg. Floor 2 teacher's room sink	10/22/16	0.001	none	
161941.11	Main Bldg. girls room sink floor 2 near grade 5	10/22/16	<0.001	none	
161941.12	Main bldg. boys room sink floor 2 near grade 5	10/22/16	<0.001	none	
161941.13	Barry Hall Kitchen faucet	10/22/16	0.003	none	
161941.14	Barry Hall Boys Room floor 2	10/22/16	<0.001	none	
161641.15	Barry Hall Girls room floor 2	10/22/16	<0.001	none	
161941.16	Barry Hall Boys Room floor 3	10/22/16	<0.001	none	
161941.17	Barry Hall Girls room floor 3	10/22/16	0.001	none	
161941.18	Parish Activity Center fountain in entranceway	10/22/16	0.009	none	
161941.19	Parish Activity Center large kitchen sink	10/22/16	0.001	none	
161941.2	Parish Activity Center small sink	10/22/16	0.002	none	
	Action is needed if lead exceeds 0.019			Testing done by Eastern Analytical Concord	
	Chart updated 3/ 11/2019 by Stephen Donohue				